

Qb- Cutting tool material

Characteristics :-

① High hot hardness

1. The material must remain harder than the work material at elevated operating temperature.

② Wear Resistance

The material must withstand incessive wear even through the relative hardness of the tool work materials changes.

③ Toughness

The toughness actually implied a combination of strength and ductility. The material must have sufficient toughness, cost and

Cost and easeness in fabrication.

The cost and easeness of fabrication should have within reasonable limits.

Composition

Types of tool material.

* Carbon tool steels

Carbon: 0.08% to 1.5%

Carbon steel contains carbon in amounts ranging from 0.08 to 1.5%.

It is used in manufacture of tools at low cutting speed about 12 m/min.

* High speed steel

High speed steel operate at 2 to 3 times more than cutting speed of the carbon steels.

To improve the hot hardness cobalt is used.

Tungsten in high speed steel provides hot hardness, molybdenum increases cleanliness, the keenness of the cutting edge.

• Cobalt improves the hot hardness and wear resistance.

Stellites

• It is the trademark of non-ferrous cast iron alloy composed of cobalt, chromium and tungsten.

• Diamond is the hardest, most-wear resistant material in the world. It is sweet suitable for cutting material glass, plastic and ceramics.

Types of

* Question

Write the different types of tool material and explain high speed steel tool material and its uses.

Properties of cutting fluid

① High heat conductivity for removal of heat from workpiece.
② Good lubricating properties to reduce friction.

③ Good chemical stability to resist oxidation and corrosion.

Cutting fluids:-

Cutting fluids, some times referred to as lubricants, and coolant's are purpose - liquid and gases applied to the tool and workpieces to assist in cutting operation,

* Purpose of cutting fluids

- ① To cool the work piece material
- ② To lubricate and reduce friction.
- ③ To improve surface finish
- ④ To prevent finish surface from corrosion.
- ⑤ To cause chips break up into small parts
- ⑥ To wash the chips away from the tool.

* Properties of cutting fluids


- ① High heat absorption & readily absorb being water develop.
- ② Good lubricate qualities, to produce low coefficient of friction

③ High flash point ^{show} so as to eliminate the hazard of fire ~~stabe~~

④ Stability show as not to oxidize in the air.

⑤ Neutral show as not to react chemically

⑥ Odorless show as not to produce any bad smell even when heated



Cutting steel


The cutting speed of the tool is the speed at which material is removed by the tool. In the case of cutting steel, the cutting speed is usually measured in feet per minute (FPM) or meters per minute (MPM). The cutting speed is affected by the material being cut, the tool material, and the cutting conditions.

Cutting speed = $\frac{1000 \times \text{rpm}}{1000}$

$\text{rpm} = \frac{1000 \times \text{cutting speed}}{1000}$

$\text{rpm} = 1000$

Chisel




(single point cutting tool)

Hack saw



(multi point cutting tool)
 Rake angle

Machining process parameter



Cutting speed

The cutting speed of the tool is the speed at which metal is removed by the tool from the workpieces (W/P) in a length lathe it is the periphery of the speed of the W/P. Cutting speed unit is ~~m~~ meter per minute

$$\text{Cutting speed} = \frac{\pi d n}{1000} \text{ m/min}$$

d = diameter of W/P

n = rpm

Feed

• The feeds of a cutting tool in a length work is that distance the tool advances for each revolution of work.

• Feed is expressed in 'mm' per revolution.

• Increased feed reduces ~~then~~ the cutting time.

• Increased feed reduces the tool life.


• The feed affects such factors such as size, ~~size~~, strength, depth of cut, power absorbable etc.

• Coarser feeds are used for roughing and final feeds for finishing cut.

Depth of cut:-

• The depth of cut is the perpendicular distance measured from the machine's table to uncut surface of the workpiece.

$$\text{Depth of cut} = \frac{D_1 - D_2}{2}$$



Where D_1 = diameter of the work shaft phase before machining
 into D_2 = diameter of the machine substance.

Depth of cut

Machining time:-

Machining time in the length work can be calculated for a particular operation if the speed of feed length of the jump is low.


The time taken for a completely cut

$$= \frac{L}{S \times n} =$$

Where L = length of the job

S = feed of job per revolution; and n

cutting tool nomenclature:



Face

The face of the cutting tool is that surface against which the chip slides upward.

SHANK


It is the part of the tool which is not ground to form the cutting edge in cross-section.

Flank

The Flank of cutting tool is that surface which faces the work piece or the continuation of the side and cutting adjacent edges.

- The nose radius increases the tool life and surfaces finish.

Single point Cutting tool.



SHANK

It is that portion of the tool which is not ground to form the cutting edges and is rectangular in cross-section.

HEEL:-

The heel of a single point cutting tool is the lowest portion of side cutting edge.


BASE:-

It is the under side of portion of the shank.

Cutting tool nomenclature:-

Cutting tool nomenclature means systematic naming of various parts, and angle of a cutting tool.

The various part of cutting tool these are shank, face, flank, heel, nose, base of back rake, side rake, side clearance angle, end cutting edges and lip angle shown in the figure.



Rake, Angle:-


The rake is the slope of the top away from the cutting edge. The change of the rake angle \therefore larger will be the shear angle and subsequently the ^{power} cutting force reduces.

- A larger rake angle is good for surface finish.



- If tool has a side and back rake angle

- Back rake indicates that the plane which forms the face or top of a tool has been ground back at an angle sloping from the nose

- Side rake indicates that the plane that forms the face or top of the tool has been ground back at an angle sloping from the side cutting edges.



Geometry of turning tool



The three views of single point cutting tool and cutting angles are shown ~~and explained~~ above and explained below.

* Side cutting edge angle - (SCEA)

* Side cutting edge angle is also known as ^{lead angle} the angle between side cutting edge and side of shank.

* End cutting edge angle - (ECEA)

End cutting edge angle
It is the angle between the end cutting edge and line normal to shank.

* Side rake angle (SRA)

Rake - It is the angle between the portion side flank in a meridian below the side cutting edge and a line perpendicular to the base of the tool and measured at right angle to side flank.

* End rake angle - (ERA)

It is the angle between the portion of end flank immediately below the end cutting edge and a line ~~perpendicular~~ to the base of the tool and measured at ~~right~~ angle to the ~~side~~ end flank.

* Back rake angle (BRA), ab. It is the angle between the face of the tool and a line parallel to the base of the tool and measured in a plane (perpendicular) through the side cutting edge.

this angle is positive, if the side cutting edge slope of the side downwards from the point toward the shank and is negative if the slope of the side cutting edge is reverse. So this angle gives the slope of the face of the tool from the nose towards the shank.

Side Rake angle :- (SR) α_s

It is the angle between the face of the tool and a line parallel to the base of the tool and measured in a plane perpendicular to the base and the side cutting edge. This angle gives the slope of the face of the tool from the cutting edge. The side rake is negative if the slope is towards the cutting edge and is positive if the slope is away from the cutting edge.

Barcode

ing

② List the various cutting operations
 ③ List the various cutting operations

Lathe operations:-

The operations which are ^{performed} cutting in a lathe either by holding the workpiece between the centers or by chucks are called state turning

- ② Taper turning.
- ③ Chamfering
- ④ Thread cutting
- ⑤ Facing
- ⑥ Knurling
- ⑦ Spinning
- ⑧ Grooving


operation which are performed by holding the work by a chuck or a face plate -

- ① Drilling
- ② Reaming.
- ③ Boring
- ④ Counter boring
- ⑤ Tapping
- ⑥ Parting


Operation which are performed by using special attachment

- ① Grinding
- ② Milling

Turning operation:-




(Rough turning)



(Finish turning)

Turning in a lathe is to remove excess material from the work pieces to produce a cylindrical surface.

In straight turning the work is turned straight when it's made to rotate about the lathe axis and tool is feed parallel to the lathe axis. The straight turning produces a cylindrical by removing extra metal from the workpiece.



The principal of turning taper by this method is to tilt the axis of rotation of workpiece at an angle to the lathe axis and feeding the tool parallel to the lathe axis. The axis angle at which

the axis of rotation to which is shifted to equal to half angle of the taper. This is done when body of test stock is made to slide on the base from the operator by a set over distance.

$$\sin \alpha = \frac{S}{L} \quad (S = \text{set over distance})$$


$$\Rightarrow S = L \sin \alpha$$

for small angle $\sin \alpha = \tan \alpha$

$$S = L \tan \alpha$$

$$\text{set over} = L \times \frac{D-d}{2l}$$


Thread cutting:-




The principle of thread cutting is to produce a helical groove on a cylindrical surface by feeding the tool longitudinally when the job is revolved between the centers or by chucks.

The longitudinal feed should be equal to the pitch of thread to be cut per revolution of work piece. The lead screw of the lathe through which the saddle receives the transverse motion has a definite pitch.


Transverse lathe



Turret lathe:-



Capstan lathe.



Capstan lathe.

The turret of capstan lathe is mounted on a short slide which slides on the saddle. The saddle is clamped on bed at any angle adjusting lathe of the workpiece. Thus in a capstan lathe the travel of turret is dependent upon the length of the travel of the ram. This limits the maximum length of the work to be machined in one setting.

Turret lathe.

The turret lathe of the turret lathe is mounted on a saddle which slides directly on the bed. This fixture enables the turret to be moved on the entire length of the bed and can machine longer work. Larger and heavier works are usually handled on a turret lathe.

Difference between lathe. capstan lathe and turret lathe.



Capstan

① It's turret (head) is mounted on an auxiliary slide which moves on the guide wire provided on the saddle.

7. ② In this case the saddle is fixed at a convenient distance from wall and the tools are fed by moving the slide.

turret

① g.p.s. turret (head) is mounted directly on the saddle.

③ for feeding tools to the work the entire saddle unit is moved.